



DEFENSE LOGISTICS AGENCY
LAND AND MARITIME
POST OFFICE BOX 3990
COLUMBUS, OH 43218-3990

January 8, 2014

Robert Wallick
Reliability Engineer
Winchester Electronics
199 Park Road Extension
Suite 104
Middlebury, CT 06762

Dear Mr. Wallick:

Re: Qualification of M55302/1, /2, /4, /5, /6, /7, /8, /16, /17, /18, /21, /22, /55, /56, /57, /58,
/59, /60, /61, /62, /63, /64, /65, /66
Test Report Number: 55302-3963-13; VQP-14-027128a
Preparing Activity: DLA-CC, FSC 5935; Control Number: 040918

This office has received your email dated October 9, 2013 along with the test data for the re-qualification of the MIL-PRF-55302 slash sheets listed above. After review, the information was found to meet the requirements of MIL-PRF-55302. The next revision of the QPL-55302 will reflect the re-qualification of the following slash sheets along with the dash numbers reflecting number of contacts; M55302/1, /2, /4, /5, /6, /7, /8, /16, /17, /18, /21, /22, /55, /56, /57, /58, /59, /60, /61, /62, /63, /64, /65, /66.

Government Designation
M55302/1-01 thru 05
M55302/2-01 thru 05
M55302/4-01 thru 06
M55302/5-01 thru 06
M55302/6-01 thru 06
M55302/7-01 thru 05
M55302/8-01 thru 05
M55302/16 -01 thru 19
M55302/17-01 thru 63
M55302/18-01 thru 21
M55302/21-01 thru 02
M55302/22-01 thru 03
M55302/55-66
M55302/57-60
M55302/58-60
M55302/59-120



M55302/60-120
M55302/61-50
M55302/62-50
M55302/63-60
M55302/64-60
M55302/65-70
M55302/66-70

This qualification is subject to the conditions stated in DoD 4120.24-M and SD-6. Because we are held responsible for the accuracy and currency of this QPL, please let us know if your company discontinues production of these products.

If you have any questions concerning this letter, please contact Ms. Sonya Taylor at 614-692-2193 or Sonya. Taylor@dla.mil.

Sincerely,

/SIGNED/

JOSEPH GEMPERLINE
Chief
Sourcing and Qualifications Division